

**Inspection Photos**  
**Location Name: Woolley #1**  
**Spill ID: 479484**



**Photo 1 Tank Battery Sign**



**Photo 2 Produced water vessel containment requiring maintenance.**



**Inspection Photos**  
**Location Name: Woolley #1**  
**Spill ID: 479484**



**Photo 3 Excavation at flowline release**



**Photo 4 Excavation overview and stockpile at flowline release.**



**Inspection Photos**  
**Location Name: Woolley #1**  
**Spill ID: 479484**



**Photo 5 Excavation at flowline release, looking south**



**Photo 6 Excavation flowline release. Stormwater accumulated in excavation.**

