

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BOSELY-67S96W /27SESE

Location ID: 334113



Photo #3710 from entrance to location.



Photo #3711 No battery sign located at the tank battery.

