

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SPECIALTY RESTAURANTS-67S96W /26SWNW

Location ID: 334702



Photo #3723 from entrance to location.



Photo #3724 from entrance to location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SPECIALTY RESTAURANTS-67S96W /26SWNW

Location ID: 334702



Photo #3725 location lacks stabilization.



Photo #3726 location lacks stabilization.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SPECIALTY RESTAURANTS-67S96W /26SWNW

Location ID: 334702



Photo #3727 No form of tracking BMP at entrance to location.



Photo #3728 No tank battery sign located at the tank battery.