

Inspection Photos
Location Name: Parmlee #3 Tank Battery
Location ID: 470289



Photo 1 – Tank Battery – Weeds



Photo 2 – Tank Battery Sign



Inspection Photos
Location Name: Parmlee #3 Tank Battery
Location ID: 470289



Photo 3 – Heater Treater



Photo 4 – Produced Water Tank – NFPA Label



Inspection Photos
Location Name: Parmlee #3 Tank Battery
Location ID: 470289



Photo 5 – Gas Meter Shed



Photo 6 – Gas Meter

Inspection Photos
Location Name: Parmlee #3 Tank Battery
Location ID: 470289




Photo 7 – Gas Meter Calibration Card NOT Updated