

**Inspection Photos**  
**Location Name: Oxbow 0880 S29**  
**Location ID: 458790**



**Photo 1. Sign at entrance incomplete/inaccurate.**



**Photo 2. Overview of location taken at entrance facing northeast.**



**Inspection Photos**  
**Location Name: Oxbow 0880 S29**  
**Location ID: 458790**



**Photo 3. Sign at wellhead incomplete/inaccurate.**



**Photo 4. Sign at wellhead incomplete/inaccurate.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Inspection Photos  
Location Name: Oxbow 0880 S29  
Location ID: 458790



Photo 5. Sign at wellhead incomplete/inaccurate.



Photo 6. Sign at wellhead incomplete/inaccurate.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos  
Location Name: Oxbow 0880 S29  
Location ID: 458790



Photo 7. Sign at wellhead incomplete/inaccurate.



Photo 8. No wellhead sign.





**Inspection Photos**  
**Location Name: Oxbow 0880 S29**  
**Location ID: 458790**



**Photo 9. Tank label incomplete/inaccurate.**



**Photo 10. Entrance sign incomplete/inaccurate.**

