

**Inspection Photos**  
**Operator: Fritz & Digman**  
**API: 067-05264**  
**Date: 5/5/2021**



Photo 1. View of the project area from the northwestern corner facing center.




Photo 2. View of the northern project area facing eastward. Dense Russian knapweed observed. Scattered smooth brome present.



Photo 3. View of the western project area facing southward.



Photo 4. View of the reference area comprised of greasewood, rabbitbrush, and sagebrush shrubland with understory of grasses such as smooth brome and crested wheatgrass.