

## Inspection Photos

Location Name: LARAMIE ENERGY LLC BCU /12D Pad

Location ID: 312363

Network time is not synchronize  
Local: May 6, 2021 at 1:32:38 PM MD



Photo #3738 from entrance to location.

Network time is not synchronize  
Local: May 6, 2021 at 1:32:41 PM MD



Photo #3739 from entrance to location.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

Location Name: LARAMIE ENERGY LLC BCU /12D Pad

Location ID: 312363

Network time is not synchronize  
Local: May 6, 2021 at 1:33:21 PM MD



**Photo #3740 No battery sign located at the tank battery.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources