

Inspection Photos

5/6/2021

Operator: GUNNISON ENERGY LLC - #10515

Location ID: 324464

Gunnison County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: GUNNISON ENERGY LLC - #10515
Location ID: 324464



Photo 1: Photo taken from the western end of the Location, facing north. Photos 1-3 provide an overview of the production areas of the Location from north, east to southeast. Equipment mob in process for construction on an adjacent Location.

Inspection Photos
Operator Name: GUNNISON ENERGY LLC - #10515
Location ID: 324464



Photo 2: See comments under photo 1.

Inspection Photos
Operator Name: GUNNISON ENERGY LLC - #10515
Location ID: 324464



Photo 3: See comments under photo 1.

Inspection Photos
Operator Name: GUNNISON ENERGY LLC - #10515
Location ID: 324464



Photo 4: Photo taken from the west end of the Location. Photo shows equipment that appears to be leaking; spill/stained soils observed around base of equipment. Ensure proper mechanical conditions of equipment to prevent further leaking and clean spill.

Inspection Photos
Operator Name: GUNNISON ENERGY LLC - #10515
Location ID: 324464



Photo 5: See comments under photo 4.

Inspection Photos
Operator Name: GUNNISON ENERGY LLC - #10515
Location ID: 324464



Photo 6: See comments under photo 4.

Inspection Photos
Operator Name: GUNNISON ENERGY LLC - #10515
Location ID: 324464



Photo 7: : Photo taken from the southern area of the production area. Photo shows various unused equipment, trash or debris observed on the Location. Remove unused equipment, trash and debris in accordance with Rule 606.

Inspection Photos
Operator Name: GUNNISON ENERGY LLC - #10515
Location ID: 324464



Photo 8: : Photo taken from the southern area of the production area. Photo shows various unused equipment, trash or debris observed on the Location. Remove unused equipment, trash and debris in accordance with Rule 606.

Inspection Photos
Operator Name: GUNNISON ENERGY LLC - #10515
Location ID: 324464



Photo 9: : Photo taken from the southern area of the production area. Photo shows various unused equipment, trash or debris observed on the Location. Remove unused equipment, trash and debris in accordance with Rule 606.

Inspection Photos
Operator Name: GUNNISON ENERGY LLC - #10515
Location ID: 324464



Photo 10: : Photo taken from the southern area of the production area. Photo shows various unused equipment, trash or debris observed on the Location. Remove unused equipment, trash and debris in accordance with Rule 606.

Inspection Photos
Operator Name: GUNNISON ENERGY LLC - #10515
Location ID: 324464



Photo 11: Photo taken from the southern area of the production area. Photo shows various unused equipment, trash or debris observed on the Location. Remove unused equipment, trash and debris in accordance with Rule 606.

Inspection Photos
Operator Name: GUNNISON ENERGY LLC - #10515
Location ID: 324464



Photo 12: Photo taken from the southern end of the Location. Photo shows various unused equipment, trash or debris observed on the Location. Remove unused equipment, trash and debris in accordance with Rule 606.

Inspection Photos
Operator Name: GUNNISON ENERGY LLC - #10515
Location ID: 324464



Photo 13: Photo taken from the northern area of the production area. Photo shows various unused equipment, trash or debris observed on the Location. Remove unused equipment, trash and debris in accordance with Rule 606.

Inspection Photos
Operator Name: GUNNISON ENERGY LLC - #10515
Location ID: 324464



Photo 14: Photo taken from the northern end of the production area. Photo shows various unused equipment, trash or debris observed on the Location. Remove unused equipment, trash and debris in accordance with Rule 606.

Inspection Photos
Operator Name: GUNNISON ENERGY LLC - #10515
Location ID: 324464



Photo 15: Photo taken from the western area of the production area. Photo shows various unused equipment, trash or debris observed on the Location. Remove unused equipment, trash and debris in accordance with Rule 606.

Inspection Photos
Operator Name: GUNNISON ENERGY LLC - #10515
Location ID: 324464



Photo 16: Photo taken from the southeastern end of the Location, facing northwest. Photo shows areas of the Location not needed for production; areas require reclamation in accordance with 1003 rules.

Inspection Photos
Operator Name: GUNNISON ENERGY LLC - #10515
Location ID: 324464



Photo 17: Photo taken from the western end of the Location, facing southeast. Photo shows areas of the Location not needed for production; areas require reclamation in accordance with 1003 rules.

Inspection Photos
Operator Name: GUNNISON ENERGY LLC - #10515
Location ID: 324464




Photo 18: 2011 Google Earth aerial imagery. Photo show equipment on the south and west ends of the Location

Inspection Photos
Operator Name: GUNNISON ENERGY LLC - #10515
Location ID: 324464



Photo 19: 2015 Google Earth aerial imagery. Photo shows equipment was removed from the south and west ends of the Location, sometime between 2011 and 2015

Inspection Photos
Operator Name: GUNNISON ENERGY LLC - #10515
Location ID: 324464



20210506

Photo 20: 5/6/2021 aerial image. Photo shows areas on the south and west ends of the Location where equipment was Location. Areas are not needed for production and require reclamation in accordance with Rule 1003.a.