

Inspection Photos

API: 009-06099

Operator: SOVEREIGN OPERATING COMPANY

Inspection Date: 5/5/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 009-06099 | Date: 5/5/2021

Inspection Photos



Photo 1. Facing west along the former access road. Perennial vegetation has re-established along the access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06099 | Date: 5/5/2021

Inspection Photos



Photo 2. There is some Noxious Weeds (Field bindweed) along the road which will need to be controlled.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06099 | Date: 5/5/2021

Inspection Photos



Photo 3. Facing west along the former access road. Perennial vegetation has re-established along the access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06099 | Date: 5/5/2021

Inspection Photos



Photo 4. Facing northeast at the location. Most of the location has re-established perennial vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06099 | Date: 5/5/2021

Inspection Photos



Photo 5. There is some Noxious Weeds (Field bindweed) at the location which will need to be controlled.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06099 | Date: 5/5/2021

Inspection Photos



Photo 6. The area highlighted contains undesirable weeds and perennial vegetation has not established in this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06099 | Date: 5/5/2021

Inspection Photos



Photo 7. View of ground cover shows undesirable weeds (Kochia) in the area of previous photo.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06099 | Date: 5/5/2021

Inspection Photos



Photo 8. Facing west at the location. Perennial vegetation has re-established in this area of the location. There is some Noxious Weeds (Field bindweed) at the location which will need to be controlled.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06099 | Date: 5/5/2021

Inspection Photos



Photo 9. Facing east at the surrounding undisturbed pasture. No weeds were observed in the surrounding reference area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06099 | Date: 5/5/2021