

# *Inspection Photos*

*API# 045-10532*

*Operator: Terra*

*Insp#: 692403354*

*Insp Date: 4/30/21*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:  
View into Location .

April 30, 2021



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Insp Photos: Terra Potter PA API#045-10532



Photo#2:  
PA Marker, view to North.

April 30, 2021



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#3:  
Vegetation, view to West

Insp Photos: Terra Potter PA API#045-10532



Photo#4:  
Riser, on North edge of Location; insert Handle Lockout, Tag out.

April 30, 2021



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Insp Photos: Terra Potter PA API#045-10532