



**Location**

Overall Good:

**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	Both Crude oil tank & Pit capacity labels are faded. See attached photos.		
Corrective Action:	Install sign to comply with Rule 605.g.	Date:	06/18/2021

Emergency Contact Number:

Comment:	Adequate	Date:	
Corrective Action:		Date:	

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	TANK BATTERY		
Comment:	Barbwire		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Panel		
Corrective Action:		Date:	
Type	IGNITOR/COMBUSTOR		
Comment:	Barbwire		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	barbwire		
Corrective Action:		Date:	

**Equipment:**

Type:			corrective date
Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Gas Meter Run	# 1		
Comment:	Gas meter appears to not have an annual calibration. Calibrate before returning to production. See attached photo.		
Corrective Action:		Date:	
Bradenhead	# 1		

Comment:	Appears to be plumbed to surface		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		40.313900,-104.473100
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		
		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	
	Date:

**Inspected Facilities**

Facility ID: 245815 Type: WELL API Number: 123-13610 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: SI

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 08/19/2019 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: --

Comment: No updated annual bradenhead test on file. Submit reports.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary                      On Monday 5/10/21 at approximately 0800hrs, I, Inspector Adam Burns, Conducted an on-site inspection at C. Watkins 18-6 of Noble Energy, at Location ID # 326755 in Weld County, Colorado.                      During this inspection the following possible compliance issues were observed:                      Both Crude oil tank &amp; Pit capacity labels are faded. Install sign to comply with Rule 605.g. With a corrective action date of 6/18/21                      Gas meter appears to not have an annual calibration. Calibrate before returning to production.                      See attached photos.                      A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.                      This is a summary of inspection report.</p>	burnsa	05/10/2021

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699103595	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5424460">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5424460</a>