

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/10/2021

Submitted Date:

05/10/2021

Document Number:

699103598

**FIELD INSPECTION FORM**Loc ID 414805 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

10 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@NB LENERGY.COM	All Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
414900	WELL	SI	07/01/2020	OW	123-30883	SATER CC 18-23	SI

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Adequate

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	TANK BATTERY		
Comment:	Barbwire		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Panel		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Barbwire		
Corrective Action:		Date:	
Type	IGNITOR/COMBUSTOR		
Comment:	barbwire		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		

Comment: <a href="#">Appears to be plumbed to surface.</a>		Date:
Corrective Action:		Date:
Type: Plunger Lift	# 1	
Comment:		
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 1	
Comment:		
Corrective Action:		Date:
Type: Emission Control Device	# 2	
Comment:		
Corrective Action:		Date:
Type: Bird Protectors	# 3	
Comment:		
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		40.309000,-104.474600
Comment:					
Corrective Action:		Date:			

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:		Date:		

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	OTHER	PBV CONCRETE		,
Comment: <a href="#">Shares containment with crude oil tank.</a>					
Corrective Action:		Date:			

**Paint**

Condition	
Other (Content)	
Other (Capacity)	48 BBL
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
------	----------	---------------------	---------------------	-------------

Comment:					
Corrective Action:					Date:
<b><u>Venting:</u></b>					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
<b><u>Flaring:</u></b>					
Type					
Comment:					
Corrective Action:					Date:

**Inspected Facilities**Facility ID: 414900 Type: WELL API Number: 123-30883 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: SI

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**BradenHead**Date of Last Brhd Test: 07/14/2020Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0

Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Monday 5/10/21 at approximately 0914hrs, I, Inspector Adam Burns, Conducted an on-site inspection at Sater CC 18-23 of Noble Energy Location ID: 414805 in Weld County, Colorado.</p> <p>While there, I observed a well that is SI.</p> <p>No violation of the COGCC rules were observed at the time of inspection.</p> <p>This is a summary of inspection report.</p>	burnsa	05/10/2021

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699103599	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5424462">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5424462</a>