

Final Reclamation Inspection

May 4, 2021

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

API: 123-22270

Inspection Document #: 697502858

Weld County, CO

SENE Section 24 T2N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: RANKIN #8-24
API: 123-22270



Photo 1. Photo taken from the well location, facing Southeast. Photo illustrates all equipment has been removed from the well location. Location is within an active gravel mine.