

**FORM  
INSP**Rev  
X/20

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

05/04/2021

Submitted Date:

05/04/2021

Document Number:

700702684

**FIELD INSPECTION FORM**

Loc ID 417399	Inspector Name: Ramsey, Scott	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input checked="" type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED  <b>Findings:</b> 23 Number of Comments 2 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested																																																																																																																										
<b>Operator Information:</b> OGCC Operator Number: 10531 Name of Operator: GRIZZLY OPERATING LLC Address: 5847 SAN FELIPE #3000 City: HOUSTON State: TX Zip: 77057				<b>ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE</b>																																																																																																																										
<b>Contact Information:</b> <table border="1" style="width:100%; border-collapse: collapse;"> <tr> <th>Contact Name</th> <th>Phone</th> <th>Email</th> <th>Comment</th> </tr> <tr> <td>, TEP</td> <td>970-285-9377</td> <td>COGCCInspectionReports@terraep.com</td> <td></td> </tr> </table>							Contact Name	Phone	Email	Comment	, TEP	970-285-9377	COGCCInspectionReports@terraep.com																																																																																																																	
Contact Name	Phone	Email	Comment																																																																																																																											
, TEP	970-285-9377	COGCCInspectionReports@terraep.com																																																																																																																												
<b>Inspected Facilities:</b> <table border="1" style="width:100%; border-collapse: collapse;"> <thead> <tr> <th>Facility ID</th> <th>Type</th> <th>Status</th> <th>Status Date</th> <th>Well Class</th> <th>API Num</th> <th>Facility Name</th> <th>Insp Status</th> </tr> </thead> <tbody> <tr><td>417402</td><td>WELL</td><td>PR</td><td>02/13/2012</td><td>GW</td><td>045-19506</td><td>GGU FEDERAL 24D-20-691</td><td>PR</td></tr> <tr><td>417407</td><td>WELL</td><td>PR</td><td>03/13/2012</td><td>GW</td><td>045-19510</td><td>GGU FEDERAL 33B-20-691</td><td>PR</td></tr> <tr><td>417413</td><td>WELL</td><td>PR</td><td>01/23/2012</td><td>GW</td><td>045-19514</td><td>GGU FEDERAL 24B-20-691</td><td>PR</td></tr> <tr><td>417416</td><td>WELL</td><td>PR</td><td>03/13/2012</td><td>GW</td><td>045-19515</td><td>GGU FEDERAL 33A-20-691</td><td>PR</td></tr> <tr><td>417418</td><td>WELL</td><td>PR</td><td>03/13/2012</td><td>GW</td><td>045-19516</td><td>GGU FEDERAL 33C-20-691</td><td>PR</td></tr> <tr><td>417419</td><td>WELL</td><td>PR</td><td>02/13/2012</td><td>GW</td><td>045-19517</td><td>GGU FEDERAL 33D-20-691</td><td>PR</td></tr> <tr><td>417421</td><td>WELL</td><td>PR</td><td>02/13/2012</td><td>GW</td><td>045-19519</td><td>GGU JOLLEY 43C-20-691</td><td>PR</td></tr> <tr><td>417424</td><td>WELL</td><td>PR</td><td>01/23/2012</td><td>GW</td><td>045-19521</td><td>GGU FEDERAL 34B-20-691</td><td>PR</td></tr> <tr><td>417442</td><td>WELL</td><td>PR</td><td>02/13/2012</td><td>GW</td><td>045-19526</td><td>GGU FEDERAL 23D-20-691</td><td>PR</td></tr> <tr><td>417445</td><td>WELL</td><td>PR</td><td>03/13/2012</td><td>GW</td><td>045-19529</td><td>GGU FEDERAL 34C-20-691</td><td>PR</td></tr> <tr><td>417454</td><td>WELL</td><td>PR</td><td>02/13/2012</td><td>GW</td><td>045-19534</td><td>GGU FEDERAL 23B-20-691</td><td>PR</td></tr> <tr><td>417464</td><td>WELL</td><td>PR</td><td>01/16/2012</td><td>GW</td><td>045-19540</td><td>GGU FEDERAL 23A-20-691</td><td>PR</td></tr> <tr><td>417465</td><td>WELL</td><td>PR</td><td>03/13/2012</td><td>GW</td><td>045-19541</td><td>GGU FEDERAL 23C-20-691</td><td>PR</td></tr> <tr><td>417472</td><td>WELL</td><td>PR</td><td>01/16/2012</td><td>GW</td><td>045-19545</td><td>GGU FEDERAL 34D-20-691</td><td>PR</td></tr> </tbody> </table>							Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	417402	WELL	PR	02/13/2012	GW	045-19506	GGU FEDERAL 24D-20-691	PR	417407	WELL	PR	03/13/2012	GW	045-19510	GGU FEDERAL 33B-20-691	PR	417413	WELL	PR	01/23/2012	GW	045-19514	GGU FEDERAL 24B-20-691	PR	417416	WELL	PR	03/13/2012	GW	045-19515	GGU FEDERAL 33A-20-691	PR	417418	WELL	PR	03/13/2012	GW	045-19516	GGU FEDERAL 33C-20-691	PR	417419	WELL	PR	02/13/2012	GW	045-19517	GGU FEDERAL 33D-20-691	PR	417421	WELL	PR	02/13/2012	GW	045-19519	GGU JOLLEY 43C-20-691	PR	417424	WELL	PR	01/23/2012	GW	045-19521	GGU FEDERAL 34B-20-691	PR	417442	WELL	PR	02/13/2012	GW	045-19526	GGU FEDERAL 23D-20-691	PR	417445	WELL	PR	03/13/2012	GW	045-19529	GGU FEDERAL 34C-20-691	PR	417454	WELL	PR	02/13/2012	GW	045-19534	GGU FEDERAL 23B-20-691	PR	417464	WELL	PR	01/16/2012	GW	045-19540	GGU FEDERAL 23A-20-691	PR	417465	WELL	PR	03/13/2012	GW	045-19541	GGU FEDERAL 23C-20-691	PR	417472	WELL	PR	01/16/2012	GW	045-19545	GGU FEDERAL 34D-20-691	PR
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status																																																																																																																							
417402	WELL	PR	02/13/2012	GW	045-19506	GGU FEDERAL 24D-20-691	PR																																																																																																																							
417407	WELL	PR	03/13/2012	GW	045-19510	GGU FEDERAL 33B-20-691	PR																																																																																																																							
417413	WELL	PR	01/23/2012	GW	045-19514	GGU FEDERAL 24B-20-691	PR																																																																																																																							
417416	WELL	PR	03/13/2012	GW	045-19515	GGU FEDERAL 33A-20-691	PR																																																																																																																							
417418	WELL	PR	03/13/2012	GW	045-19516	GGU FEDERAL 33C-20-691	PR																																																																																																																							
417419	WELL	PR	02/13/2012	GW	045-19517	GGU FEDERAL 33D-20-691	PR																																																																																																																							
417421	WELL	PR	02/13/2012	GW	045-19519	GGU JOLLEY 43C-20-691	PR																																																																																																																							
417424	WELL	PR	01/23/2012	GW	045-19521	GGU FEDERAL 34B-20-691	PR																																																																																																																							
417442	WELL	PR	02/13/2012	GW	045-19526	GGU FEDERAL 23D-20-691	PR																																																																																																																							
417445	WELL	PR	03/13/2012	GW	045-19529	GGU FEDERAL 34C-20-691	PR																																																																																																																							
417454	WELL	PR	02/13/2012	GW	045-19534	GGU FEDERAL 23B-20-691	PR																																																																																																																							
417464	WELL	PR	01/16/2012	GW	045-19540	GGU FEDERAL 23A-20-691	PR																																																																																																																							
417465	WELL	PR	03/13/2012	GW	045-19541	GGU FEDERAL 23C-20-691	PR																																																																																																																							
417472	WELL	PR	01/16/2012	GW	045-19545	GGU FEDERAL 34D-20-691	PR																																																																																																																							
<b>General Comment:</b>																																																																																																																														

COGCC Inspection Report Summary

On Tuesday 5/4/2021 at approximately 1100, I, Inspector Scott Ramsey, conducted a follow up inspection at TEP MDP 10, at Location # 417399 in Garfield county Colorado.

While there, I observed normal production operations. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat and Wildlife Management Area. Also location is within or in close proximity to the 411 water protection area. Operator (TERRA) has provided there Piceance Basin Storm water Manual of BMP's (SC-4) for a tracking pad, there is no evidence of a tracking pad at time of inspection.

During this inspection the following new compliance issues were observed:

1. Location shows signs of lack of stabilization/compaction
2. Missing tank battery signage

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

### Location

<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Missing tank battery signage		
Corrective Action:	Comply with rule 605.e	Date:	06/04/2021

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	DEBRIS		
Comment:			
Corrective Action:		Date:	

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	

<b>Equipment:</b>				corrective date
Type: Horizontal Heated Separator	# 14			
Comment:				
Corrective Action:				Date:
Type: Emission Control Device	# 1			
Comment:	tied into tank battery			
Corrective Action:				Date:
Type: Ancillary equipment	# 4			
Comment:	Two chemical tanks at well heads in plastic containments and two 500 gallon tanks at compressor in metal containments			
Corrective Action:				Date:
Type: Plunger Lift	# 14			
Comment:				
Corrective Action:				Date:
Type: Bradenhead	# 14			
Comment:	Braden heads have a port for manual gauge monitoring			
Corrective Action:				Date:
Type: Compressor	# 1			
Comment:				
Corrective Action:				Date:
Type: Bird Protectors	# 12			
Comment:				
Corrective Action:				Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	8	500 BBLS	HEATED STEEL AST		,
Comment:	Three (3) tanks are NOT heated				
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
--------	----	--

Comment:			
Corrective Action:		Date:	
<b>Flaring:</b>			
Type	Ignitor/Combustor		
Comment:	tied to tank battery		
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	417402	Type:	WELL	API Number:	045-19506	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	417407	Type:	WELL	API Number:	045-19510	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	417413	Type:	WELL	API Number:	045-19514	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	417416	Type:	WELL	API Number:	045-19515	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	417418	Type:	WELL	API Number:	045-19516	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	417419	Type:	WELL	API Number:	045-19517	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	417421	Type:	WELL	API Number:	045-19519	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	417424	Type:	WELL	API Number:	045-19521	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:						Date:			

Facility ID:	417442	Type:	WELL	API Number:	045-19526	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	417445	Type:	WELL	API Number:	045-19529	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	417454	Type:	WELL	API Number:	045-19534	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	417464	Type:	WELL	API Number:	045-19540	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	417465	Type:	WELL	API Number:	045-19541	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	417472	Type:	WELL	API Number:	045-19545	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:						Date:			

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						
Ditches						
		Culverts				
Compaction	Fail					
		Ditches				

Comment: This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat and Wildlife Management Area. Also location is within or in close proximity to the 411 water protection area. Operator (TERRA) has provided there Piceance Basin Storm water Manual of BMP's (SC-4) for a tracking pad, there is no evidence of a tracking pad at time of inspection.  
1. Location shows signs of lack of stabilization/compaction

Corrective Action: **Install or repair required BMPs**

Date: 06/04/2021

Pits: ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402679868	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5420557">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5420557</a>
700702686	photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5420548">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5420548</a>