

Inspection Photos

5/11/2021

Operator: LARAMIE ENERGY LLC - 10433

Location ID: 335190

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335190



Photo 1: Photo taken from the production area, facing south. Photo shows control measures to stabilize the production areas/access road and to prevent off-location sediment transport during wet conditions have not been maintained in proper functioning condition.



Photo 2: Photo taken from the production area, facing northwest. Photo shows control measures to stabilize the production areas/access road and to prevent off-location sediment transport during wet conditions have not been maintained in proper functioning condition.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335190



Photo 3: Photo taken from the west end of the production area, facing southwest. Photo shows control measures to stabilize the production areas/access road and to prevent off-location sediment transport during wet conditions have not been maintained in proper functioning condition.



Photo 4: Photo taken from the southwest end of the production area, facing northeast. Photo shows control measures to stabilize the production areas/access road and to prevent off-location sediment transport during wet conditions have not been maintained in proper functioning condition.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335190



Photo 5: Photo taken from the access road, southwest of the tank, facing northeast. Photo shows control measures to stabilize the production areas/access road and to prevent off-location sediment transport during wet conditions have not been maintained in proper functioning condition.



Photo 6: Photo taken from the access road entrance, facing north. Cattle guard has filled with sediment. Deep ruts observed along areas of access road.

