

Inspection Photos

5/11/2021

Operator: LARAMIE ENERGY LLC - 10433

Location ID: 335149

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335149



Photo 1: Photo taken from the west end of the production area, facing north. Photos 1-4 provide an overview of the Location from north, northeast, southeast to south.



Photo 2: See comments under photo 1.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335149



Photo 3: See comments under photo 1.



Photo 4: See comments under photo 1.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335149



Photo 5: Photo taken from the tank battery. Photo shows control measures to stabilize the production area are missing or insufficient.



Photo 6: Photo taken from the tank battery. Photo shows control measures to stabilize the production area are missing or insufficient.

Inspection Photos

Operator Name: LARAMIE ENERGY LLC - 10433

Location ID: 335149



Photo 7: Photo taken from the cut slopes on the west end of the Location. BMPs to provide long term protection and stabilization are missing or insufficient.



Photo 8: Photo taken from the cut slopes on the west end of the Location. BMPs to provide long term protection and stabilization are missing or insufficient.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335149



Photo 9: Photo taken from the access road. Photo shows erosion degradation along access road.



Photo 10: Photo taken from the access road entrances, facing southwest. Photo shows BMPs to stabilize production areas/access road and to prevent off-location sediment transport during wet conditions are missing or insufficient