

Inspection Photos
Location Name: RMPCO Kissler 1
Location ID: 319247



Production facility



Wellhead

Inspection Photos
Location Name: RMPCO Kissler 1
Location ID: 319247



Produced water vault placards



Produced water vault uncovered openings

Inspection Photos
Location Name: RMPCO Kissler 1
Location ID: 319247



Crude oil tank clean out plate leak



North berm wall