

Inspection Photos  
Location Name: Vonasek 1 TB  
Location ID: 333302



Photo 1 TB sign

Photo 2 Stained soil by Crude Tank Load out line

**Inspection Photos**  
**Location Name: Vonasek 1 TB**  
**Location ID: 333302**



**Photo 3 Missing Bird Protector**

**Photo 4 Bird Protector lying on the ground next to Horiz. Heated Sep.**