

Inspection Photos
Location Name: Vonasek 1
Location ID: 333302



Photo 1 WH sign old operator #s on sign

Photo 2 Dead weeds around WH

Inspection Photos
Location Name: Vonasek 1
Location ID: 333302



Photo 3 Dead weeds around location

Photo 4 TB sign

Inspection Photos
Location Name: Vonasek 1
Location ID: 333302



Photo 5 TB placard missing from crude tank

Photo 6 Stained soil by Crude Tank Load out line

Inspection Photos
Location Name: Vonasek 1
Location ID: 333302



Photo 7 Missing Bird Protector

Photo 8 Bird Protector lying on the ground next to Horiz. Heated Sep.

Inspection Photos
Location Name: Vonasek 1
Location ID: 333302



Photo 9 stained soil around Horiz. Heated Sep.

Photo 10 stained soil around Horiz. Heated Sep.



Inspection Photos
Location Name: Vonasek 1
Location ID: 333302



Photo11 stained soil around Horiz. Heated Sep.

Photo 12 stained soil around Horiz. Heated Sep.

Inspection Photos
Location Name: Vonasek 1
Location ID: 333302



Photo 13 Vert. Sep.

Photo 14 Gas Meter Run no indication of calibration status.