

Inspection Photos
Location Name: Sydney Strear 6
Location ID: 318347



Photo 1 WH sign



Photo 2 stained soil around WH

Inspection Photos
Location Name: Sydney Strear 6
Location ID: 318347



Photo 3 stained soil around WH



Photo 4 stained ground at pump jack base

Inspection Photos
Location Name: Sydney Strear 6
Location ID: 318347



Photo 5 leaking seals on PJ



Photo 6 stained ground at pump jack base

Inspection Photos
Location Name: Sydney Strear 6
Location ID: 318347



Photo 7 leaking seals on PJ



Photo 8 ancillary equipment