

Final Reclamation Inspection

May 12, 2021

Operator: TIMBERLINE ENERGY INC - 88348

Location ID: 322176

Inspection Document #: 697502895

Elbert County, CO

SWNW Section 2 T6S R65W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: ERICKSON #2-5
Location ID: 322176



Photo 1. Photo taken from the location, facing Southwest. Photo illustrates the location lack any establishment of vegetative growth. There was some establishment of desirable plant species but much of the location and access road lack establishment of vegetative growth that is reflective of reference area levels.



Photo 2. Photo taken from the location, facing South. See comments under Photo 1.

Inspection Photos
Location Name: ERICKSON #2-5
Location ID: 322176



Photo 3. Photo taken from the location, facing Southeast. See comments under Photo 1.



Photo 4. Photo taken from the location, facing East. See comments under Photo 1.

Inspection Photos
Location Name: ERICKSON #2-5
Location ID: 322176



Photo 5. Photo taken from the western access road, facing West. Photo illustrates some establishment of vegetation but there is observed stormwater erosion.



Photo 6. Photo taken from the western access road, facing East. See comments under Photo 5.

Inspection Photos
Location Name: ERICKSON #2-5
Location ID: 322176



Photo 7. Photo taken from the eastern access road, facing East. ee comments under Photo 5.



Photo 8. Photo taken from the eastern access road, facing South. See comments under Photo 5.