

Inspection Photos

API: 061-06456

Operator: BERRY ENERGY INC

Inspection Date: 5/12/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06456 | Date: 5/12/2021

Inspection Photos



Photo 1. Drone aerial photo facing northwest toward the location. There is a two track road that passes thru the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06456 | Date: 5/12/2021

Inspection Photos



Photo 2. Drone aerial photo facing southeast toward the location. The area which is circled is bare of vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06456 | Date: 5/12/2021