

Inspection Photos

API: 061-06303

Operator: BERRY ENERGY INC

Inspection Date: 5/12/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06303 | Date: 5/12/2021

Inspection Photos



Photo 1. Facing north along the former access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06303 | Date: 5/12/2021

Inspection Photos




Photo 2. Drone aerial photo facing southwest toward the location. Red arrow points to tank battery site. Yellow arrow points to the well site. The vegetation has not re-established in the disturbance area. Reclamation has not been completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06303 | Date: 5/12/2021

Inspection Photos



Photo 3. Facing south toward the well site. The location remains mostly devoid of vegetation growth. There is no indication that reclamation was performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06303 | Date: 5/12/2021

Inspection Photos



Photo 4. Facing south toward the battery site. The location remains mostly devoid of vegetation growth. There is no indication that reclamation was performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06303 | Date: 5/12/2021

Inspection Photos




Photo 5. Facing south toward the surrounding undisturbed pasture which shows a uniform vegetation cover.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06303 | Date: 5/12/2021