

**Inspection Photos
Cosslet A 9 Flowline
Spill ID 478542 (AC)**



Photo 1 – Spill area.



Photo 2 – Open excavation. Free product observed on groundwater. Impacts remain in situ.

**Inspection Photos
Cosslet A 9 Flowline
Spill ID 478542 (AC)**



Photo 3 – Soils stored on location with inadequate BMPs



Photo 4 – Soils stored on location with inadequate BMPs