

## Inspection Photos

Location Name: Robert G Berge #2

Spill ID 476918 (CL)/ Remediation Project No. 15743



**Photo 1 – Spill area. Excavation has been backfilled disturbed surfaces have been ripped. Canal is now active.**



**Photo 2 – Rebuilt ditch wall**