

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/18/2021

Submitted Date:

05/18/2021

Document Number:

699103686

FIELD INSPECTION FORM

Loc ID 306174 Inspector Name: Burns, Adam On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1001 NOBLE ENERGY WAY
City: HOUSTON State: TX Zip: 77070

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

6 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		NBL_DJBU_Inspections@NB LENERGY.COM	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
286093	WELL	SI	05/01/2020	GW	123-24125	Sater USX CC 19-01	SI

General Comment:

(This area is intentionally left blank for general comments.)

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	Panel		
Corrective Action:		Date:	

Equipment:

Type: Plunger Lift	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface.		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 286093 Type: WELL API Number: 123-24125 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: SI

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 07/02/2020 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 11 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
COGCC Inspection Report Summary On Tuesday 5/18/21 at approximately 1038hrs, I, Inspector Adam Burns, Conducted an on-site inspection at Sater USX CC 19-01 of Noble Energy Location ID: 306174 in Weld County, Colorado. While there, I observed a well that is SI. No violation of the COGCC rules were observed at the time of inspection. This is a summary of inspection report	burnsa	05/18/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699103687	Inspection Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5432168