

Final Reclamation Inspection

May 18, 2021

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

Location ID: 327221

Inspection Document #: 697502901

Weld County, CO

NWNW Section 34 T3N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: HSR-KINYON #4-34
Location ID: 327221



Photo 1. Photo taken from the southern well location access road, facing North. Photo illustrates Operator has performed final reclamation activities but will remain in-process.



Inspection Photos
Location Name: HSR-KINYON #4-34
Location ID: 327221



Photo 2. Photo taken from the southern well location access road, facing West. Photo illustrates a List B Colorado noxious weed, Scotch thistle, in the rosette growth stage.

Inspection Photos
Location Name: HSR-KINYON #4-34
Location ID: 327221



Photo 3. Photo taken from the central well location access road, facing North. See comments under Photo 1.



Inspection Photos

Location Name: HSR-KINYON #4-34

Location ID: 327221



Photo 4. Photo taken from the well location, facing North. See comments under Photo 2.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 697502901

Inspection Photos
Location Name: HSR-KINYON #4-34
Location ID: 327221



Photo 5. Photo taken from the well location, facing West. See comments under Photo 1.



Inspection Photos
Location Name: HSR-KINYON #4-34
Location ID: 327221



Photo 6. Photo taken from the well location, facing South. See comments under Photo 1.



Inspection Photos
Location Name: HSR-KINYON #4-34
Location ID: 327221



Photo 7. Photo taken from the well location, facing East. See comments under Photo 1.



Inspection Photos
Location Name: HSR-KINYON #4-34
Location ID: 327221



Photo 8. Reference photo taken east of the well location access road, facing East. See comments under Photo 1.