



- Photo 1 – View north toward wellhead from junction of access road and tank battery area






- Photo 2 – View northwest toward wellhead from southeast corner of well pad





- Photo 3 – View northwest from wellhead toward northwest corner of well pad





- Photo 4 – View northeast from wellhead toward northeast corner of well pad





- Photo 5 – View southwest from wellhead toward southwest corner of well pad





- Photo 6 – View south from well pad





- Photo 7 – View south from north of the former tank battery and separator area further south





- Photo 8 – View east from northwest corner of the former tank battery





- Photo 9 – View south from northwest corner of the former tank battery





- Photo 10 – View southwest across former pit area, some erosion notable in center of picture





- Photo 11 – View south across former pit area, some erosion notable in upper third of picture





- Photo 12 – View southeast across former pit area, some erosion notable in upper third of picture





- Photo 13 – View southwest across former pit area, some erosion notable through center of picture





- Photo 14 – View north across east side of former pit area toward tank battery and wellhead areas