



- Photo 1 –



- Photo 2 – Minor oil stained soil at meter shed





- Photo 3 –





- Photo 4 – Minor crude leak at separator, control leaks and properly dispose crude and leak containers





- Photo 5 – Tank on right side of picture needs NFPA placard





- Photo 6 – Remove unused equipment





- Photo 7 – Oil on west bank of produced water pit





- Photo 8 – Oil on west bank of produced water pit





- Photo 9 – Oil on west bank of produced water pit above previous photo





- Photo 10 – Oil skim tank view south toward tank battery





- Photo 11 –





- Photo 12 – Chemical tank requires secondary containment





- Photo 13 –