

Inspection Photos

5/14/2021

Operator: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335961

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335961



Photo 1: Photo taken from the west end of the Location, facing north. Photos 1-4 provide an overview of the Location from north, northeast, southeast to south. Photos show that interim reclamation of the Location has not been conducted in accordance with 1003 Rules.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335961



Photo 2: See comments under photo 1.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 335961



Photo 3: See comments under photo 1.



Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 335961



Photo 4: See comments under photo 1.



Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335961



Photo 5: Photo taken from the wells. Permits for undrilled wells on the Location have been deleted. Photo shows conductor settings/cellars require closure and reclamation in accordance with Rule 406.e.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources