

Inspection Photos

Location Name: LARAMIE ENERGY LLC Vega /5 Pad

Location ID: 334425



Photo #3869 from entrance to location.



Photo #3870 from entrance to location.

Inspection Photos

Location Name: LARAMIE ENERGY LLC Vega /5 Pad

Location ID: 334425



Photo #3871 No battery sign located at the tank battery