

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402698907

Date Received:
05/24/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Evins, Bret

bret.evins@state.co.us

NBL_DJBU_Inspections@NBLENERGY.COM

COGCC INSPECTION SUMMARY:

FIR Document Number: 699103438

Inspection Date: 04/23/2021

FIR Submit Date: 04/23/2021

FIR Status: _____

Inspected Operator Information:

Company Name: NOBLE ENERGY INC

Company Number: 100322

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

LOCATION - Location ID: 441841

Location Name: 70 Ranch State Number: BB18-655 County: _____
Multi

Qtrqr: NESE Sec: 17 Twp: 5N Range: 63W Meridian: 6

Latitude: 40.398440 Longitude: -104.452910

FACILITY - API Number: 05-123- -00 Facility ID: 441841

Facility Name: 70 Ranch State Number: BB18-655
Multi

Qtrqr: NESE Sec: 17 Twp: 5N Range: 63W Meridian: 6

Latitude: 40.398440 Longitude: -104.452910

CORRECTIVE ACTIONS:

1 CA# 150013

Corrective Action: Comply with Rule 606

Date: 05/04/2021

Response: CA COMPLETED

Date of Completion: 04/28/2021

Operator
Comment:

Trash in question has been removed

COGCC Decision: _____

COGCC
Representative:

2 CA# 150014

Corrective Action: "Properly dispose of oily waste in accordance with 905.e."

Date: 05/04/2021

Response: CA COMPLETED

Date of Completion: 04/28/2021

Operator
Comment:

Oily waste in question has been removed

COGCC Decision: _____

COGCC
Representative:

3 CA# 150015

Corrective Action: Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.

Date: 05/04/2021

Response: CA COMPLETED

Date of Completion: 04/28/2021

Operator
Comment:

Equipment in question has been secured

COGCC Decision: _____

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Alan Figurski

Signed:

Title: WSS

Date: 5/24/2021 2:03:43 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

--	--

Total Attach: 0 Files