

Inspection Photos

API: 071-08564

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 5/24/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08564 | Date: 5/24/2021

Inspection Photos



Photo 1. Facing southwest along the access road. There are areas along the road that have vehicle rutting and erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08564 | Date: 5/24/2021

Inspection Photos



Photo 2. Facing southwest along the access road. There are areas along the road that have vehicle rutting and erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08564 | Date: 5/24/2021

Inspection Photos



Photo 3. Facing northwest toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08564 | Date: 5/24/2021

Inspection Photos



Photo 4. Well sign is posted at the meter shed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08564 | Date: 5/24/2021