

Inspection Photos

API: 071-09543

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 5/24/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-09543 | Date: 5/24/2021

Inspection Photos



Photo 1. Facing south at the location. There is an erosion channel down the center of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09543 | Date: 5/24/2021

Inspection Photos



Photo 2. Facing southwest along the slope. It appears noxious weeds had been cut during previous growing season however, it is unknown if seed heads were bagged and removed. This area will need additional seeding to establish vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09543 | Date: 5/24/2021

Inspection Photos



Photo 3. There was a few Scotch thistle plants that have emerged. Follow up weed control will need to be performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09543 | Date: 5/24/2021

Inspection Photos



Photo 4. Facing northeast at the location. Vegetation has not yet established in this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09543 | Date: 5/24/2021

Inspection Photos



Photo 5. Facing north at the location. There is an erosion channel down the center of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09543 | Date: 5/24/2021

Inspection Photos



Photo 6. Facing along the southeast slope of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09543 | Date: 5/24/2021

Inspection Photos



Photo 7. Facing west at the surrounding undisturbed area which consists of a uniform native vegetation cover.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09543 | Date: 5/24/2021