

Inspection Photos

5/21/2021

Operator: GUNNISON ENERGY LLC - 10515

Location ID: 324457

Gunnison County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos

Operator Name: GUNNISON ENERGY LLC - 10515

Location ID: 324457



Photo 1: Photo taken from the access road, facing northeast. Photo shows Location remains out of compliance with 1004 rules and corrective actions; Final reclamation of the Location/access road has not been completed.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: GUNNISON ENERGY LLC - 10515

Location ID: 324457



Photo 2: Photo taken from the west end of the Location, facing east. Photo shows Location remains out of compliance with 1004 Rules and corrective actions; Final reclamation of the Location/access road has not been completed; gravel remaining on Location/Access road; compaction concerns evident; Large areas not revegetating.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: GUNNISON ENERGY LLC - 10515

Location ID: 324457



Photo 3: Photo taken from the northwest end of the Location. Photo shows anchor equipment remains on the location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator Name: GUNNISON ENERGY LLC - 10515
Location ID: 324457



Photo 4: Photo taken from the east end of the Location, facing west. See comments under photo 1.



Inspection Photos
Operator Name: GUNNISON ENERGY LLC - 10515
Location ID: 324457



Photo 5: Photo taken from the southeastern areas of the location. Photo shows areas where production equipment was located. Gravel has not been removed from areas, compaction alleviation not performed as well as revegetation. Noxious weeds observed in these areas.

