



Whiting Oil & Gas Corporation

NELSON RANCHES A1 CORRECTIVE ACTION INSPECTION PHOTOS

Location ID: 246135
NWNE Sec 18 T10N R58W

5-5-2021



Peeling/Fading Wellhead Information Fixed