

Inspection Photos
Location Name: Walker 12-3
Location ID: 313148



Photo 1. Overview of location taken facing north.



Photo 2. No bradenhead access apparent.

