

Inspection Photos
Location Name: Black Hollow 8-67-16 3H
Location ID: 428546



Photo 1: Pumpjack Sign



Photo 2: Unused equipment removed



Inspection Photos
Location Name: Black Hallow 8-67-16 3H
Location ID: 428546



Photo 3: Steps fixed



Photo 4: BBLs installed

Inspection Photos
Location Name: Black Hallow 8-67-16 3H
Location ID: 428546



Photo 5: BBLs installed

