

Inspection Photos
Operator: Simcoe
API: 067-06483
Date: 5/24/2021



Photo 1. View of project area from the well pad entrance facing center.



Photo 2. View of the western project area from the northwestern corner facing southward. Revegetation is progressing in with western wheatgrass, sagebrush, and rubber rabbitbrush.



Photos 3. View of the northern project area from the northwestern corner facing eastward.



Photo 4. View of reference area comprised of open sagebrush and western wheatgrass shrubland with scattered fourwing salt bushes and greasewood.