

XTO  
T32X-33G  
Location # 316301



location



location



XTO  
T32X-33G  
Location # 316301



location



location/lack of battery signage



XTO  
T32X-33G  
Location # 316301



**Erosion on fill slope**



**Erosion on fill slope**



XTO  
T32X-33G  
Location # 316301



**Erosion on fill slope**



**Erosion on fill slope**



XTO  
T32X-33G  
Location # 316301



**Sediment migration**



**Erosion on fill slope**



XTO  
T32X-33G  
Location # 316301



**Lack of stabilization/compaction**



**Lack of stabilization/compaction**



XTO  
T32X-33G  
Location # 316301



**Lack of stabilization/compaction**



**Lack of stabilization/compaction**