

Inspection Photos

5/26/2021

Operator: CAERUS PICEANCE LLC #10456

Location ID: 415182

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 415182



Photo 1: Photo taken from the east end of the Location, facing south. Photos 1-4 provide an overview of the Location from south, southwest, northwest to north.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 415182



Photo 2: See comments under photo 1.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 415182



Photo 3: See comments under photo 1. .

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 415182



20210526

Photo 4: See comments under photo 1.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 415182



Photo 5: Photo taken from the interim areas on the east end of the Location; interim areas progressing towards 1003 standards.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 415182



Photo 6: Photo taken from the northern interim areas of the Location. Photo shows musk thistle remnants from the 2020 growing season.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 415182



Photo 7: Photo shows noxious weed rosettes observed on the north end of the Location.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 415182



Photo 8: Photo taken from the north end of the Location. Photo shows unused pipe equipment.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 415182



Photo 9: Photo taken from the north end of the Location. Photo shows unused hose equipment.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 415182



Photo 10: Photo shows unused equipment observed on the west end of the Location. Equipment requires removal pursuant with Rule 606.a