

**Inspection Photos**  
**Location Name: Behring #1**  
**Location ID: 317496**



**Photo 1 – Wellhead**



**Photo – Stained Soil at Wellhead has been mitigated**

**Inspection Photos**  
**Location Name: Behring #1**  
**Location ID: 317496**



**Photo 3 – Bradenhead has NOW been plumbed to surface**



**Photo 4 – Stained Soil at Gas Engine has been mitigated**



**Inspection Photos**  
**Location Name: Behring #1**  
**Location ID: 317496**



**Photo 5 – Tank Battery – 500 BBL Tank is scheduled to be removed. 210 BBL Tank to remain – Deemed NOT Visible from Roadway and Rust NOT a Mechanical Issue at this time.**



**Photo 6 – Berm at Tank Battery have been resolved.**

**Inspection Photos**  
**Location Name: Behring #1**  
**Location ID: 317496**



**Photo 7 – Back Side of Tanks**



**Photo 8 – Heater Treater and 40 BBL Produced Water Tank**



**Inspection Photos**  
**Location Name: Behring #1**  
**Location ID: 317496**



**Photo 9 – Inside of Treater Shed**




**Photo 10 – Pit Area. Unmarked Riser**



**Inspection Photos**  
**Location Name: Behring #1**  
**Location ID: 317496**



**Photo 11 – Pit Area**



**Photo 12 – Dirt Farm Area. Current Soil Test Waiting Sample Results**