


**Inspection Photos**  
**Location Name: Johnson, Vern 1-A**  
**Location ID: 322867**



**Photo #1 Location**



**Photo #2 Meter run will need to be calibrated before returning to production.**

**Inspection Photos**  
**Location Name: Johnson, Vern 1-A**  
**Location ID: 322867**



**Photo #3 Bird Protector that appears to have come from the separator.**



**Photo #4 Appears the bird protector fell off.**