

Final Reclamation Inspection

May 25, 2021

Operator: GREAT WESTERN OPERATING COMPANY LLC- #10110

Location ID: 319776

Inspection Document #: 697502955

Adams County, CO

NENE Section 10 T1S R65W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos

Location Name: GREAT WESTERN WAGNER #41-10

Location ID: 319776



Photo 1. Photo taken from the entrance of location, facing West. Photo illustrates some establishment of desirable plant species but the access road consisted mostly of weedy annual which is not reflective of reference areas.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 697502955

Inspection Photos

Location Name: GREAT WESTERN WAGNER #41-10

Location ID: 319776



Photo 2. Photo taken from the eastern location, facing West.
See comments under Photo 1.



Photo 3. Photo taken from the eastern location, facing South.
See comments under Photo 1.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 697502955

Inspection Photos

Location Name: GREAT WESTERN WAGNER #41-10

Location ID: 319776



Photo 4. Photo taken from the southern location, facing West. Photo illustrates the southern location lacks establishment of desirable plant species.



Photo 5. Photo taken from the southern area. Photo illustrates a List B Colorado noxious weed, Scotch thistle.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 697502955

Inspection Photos

Location Name: GREAT WESTERN WAGNER #41-10

Location ID: 319776



Photo 6. Photo taken from the western location, facing East. Photo illustrates the southern location lacks establishment of desirable plant species.



Photo 7. Photo taken from the northwestern location, facing East. Photo illustrates the northern location lacks establishment of desirable plant species.

Inspection Photos

Location Name: GREAT WESTERN WAGNER #41-10

Location ID: 319776



Photo 8. Photo taken from the northern location, facing East. See comments under Photo 7.



Photo 9. Reference photo taken from the northern location, facing North. Photo illustrates the location is not reflective of reference area vegetative levels.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 697502955