

Final Reclamation Inspection

May 25, 2021

Operator: CONFLUENCE DJ LLC - #10518

Location ID: 320274

Inspection Document #: 697502961

Adams County, CO

SWSW Section 4 T1S R65W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: HASKINS #1
Location ID: 320274



Photo 1. Photo taken from the southern well location, facing North. Photo illustrates gravel has not been removed and final reclamation activities have not been performed. Photo also illustrates undesirable plant species which are spreading off location.

Inspection Photos
Location Name: HASKINS #1
Location ID: 320274



Photo 2. Photo taken from the well location, facing North. See comments under Photo 1.



Photo 3. Photo taken from the well location, facing Northwest. See comments under Photo 1.



Inspection Photos
Location Name: HASKINS #1
Location ID: 320274



Photo 4. Photo taken from the well location, facing East. See comments under Photo 1.



Photo 5. Photo taken from the southern well location, facing Northeast. Photo illustrates the main access road appears to be pre-existing which is access to a ditch crossing further to the northeast.

Inspection Photos
Location Name: HASKINS #1
Location ID: 320274



Photo 6. Reference photo taken east of location, facing East.