

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

06/02/2021

Submitted Date:

06/02/2021

Document Number:

699103800

FIELD INSPECTION FORM
 Loc ID 426349 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

9 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|-------|--|---------------------------------|
| , | | NBL_DJBU_Inspections@NB LENERGY.COM | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|-----------------|--------|-------------|------------|---------|--------------------------------------|-------------|
| 480013 | TANK BATTERY | AC | 05/18/2021 | | - | 31-4N-63W NWNE Booth Tank Battery | SI |

General Comment:

Location

Overall Good: ☒

| | | | |
|----------------------|---|-------|------------|
| Signs/Marker: | | | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | Pit Capacity label is faded and needs to be replaced. | | |
| Corrective Action: | Install sign to comply with Rule 605.g. | Date: | 06/11/2021 |
| Type | BATTERY | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment: Adequate

Corrective Action:

Date: _____

Overall Good: ☒

| | | | | |
|----------------|------|--------|--|--|
| Spills: | | | | |
| Type | Area | Volume | | |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

| | | | |
|--------------------|-------------------|-------|--|
| Fencing/: | | | |
| Type | SEPARATOR | | |
| Comment: | Barbwire | | |
| Corrective Action: | | Date: | |
| Type | IGNITOR/COMBUSTOR | | |
| Comment: | Panel | | |
| Corrective Action: | | Date: | |
| Type | TANK BATTERY | | |
| Comment: | Barbwire | | |
| Corrective Action: | | Date: | |

| | | | |
|-----------------------------------|---|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Horizontal Heated Separator | # 2 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Emission Control Device | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 2 | | |
| Comment: | Will need calibrated if put back into production. | | |
| Corrective Action: | | Date: | |
| Type: Bird Protectors | # 3 | | |

| | | |
|--------------------|--|-------|
| Comment: | | |
| Corrective Action: | | Date: |

Tanks and Berms:

| | | | | | |
|--------------------|--|----------|----------------|---------|--------|
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| PRODUCED WATER | 1 | 100 BBLs | PBV FIBERGLASS | | , |
| Comment: | Shares containment with crude oil tanks. | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | | | | |
|------------------|--|--|--|--|--|
| Condition | | | | | |
| Other (Content) | | | | | |
| Other (Capacity) | | | | | |
| Other (Type) | | | | | |

Berms

| | | | | |
|--------------------|----------|---------------------|---------------------|-------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| | | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

| | | | | | |
|--------------------|---|----------|-----------|---------|-----------------------|
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| CRUDE OIL | 2 | 300 BBLs | STEEL AST | | 40.276000,-104.478500 |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | | | | |
|------------------|----------|--|--|--|--|
| Condition | Adequate | | | | |
| Other (Content) | | | | | |
| Other (Capacity) | | | | | |
| Other (Type) | | | | | |

Berms

| | | | | |
|--------------------|----------|---------------------|---------------------|-------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Venting:

| | | |
|--------------------|----|-------|
| Yes/No | NO | |
| Comment: | | |
| Corrective Action: | | Date: |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

Inspected FacilitiesFacility ID: 480013 Type: TANK API Number: - Status: AC Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: SI

Corrective Action: _____

Date: _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------|---|
| 699103801 | Inspection Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5445570 |