

Final Reclamation Inspection

May 25, 2021

Operator: EXTRACTION OIL & GAS INC - #10459

Location ID: 320372

Inspection Document #: 697502968

Adams County, CO

SWNW Section 9 T1S R65W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: KALLSEN 12-9 #3
Location ID: 320372



Photo 1. Photo taken from the central associated offsite tank battery location, facing South. Photo illustrates the establishment of desirable species throughout the southern $\frac{2}{3}$ of the location.

Inspection Photos
Location Name: KALLSEN 12-9 #3
Location ID: 320372



Photo 2. Photo taken from the northern associated offsite tank battery location, facing Southeast. Photo illustrates the bare ground which appears to be associated with a disturbance post reclamation efforts.



Photo 3. Photo taken from the northern associated offsite tank battery location, facing East. See comments under Photo 2.

Inspection Photos
Location Name: KALLSEN 12-9 #3
Location ID: 320372



Photo 4. Photo taken from the northern associated offsite tank battery location, facing Northeast. See comments under Photo 2.



Photo 5. Photo taken from the northern well location access road, facing South. Photo illustrates a locked gate so COGCC staff could only inspect the tank battery.