



WELLHEAD ABANDONMENT FORM

SITE NAME: Moser 41-28							DATE: 5/24/2021	REM. PROJECT #:	WEATHER: Sunny 70 degrees		
SITE DIRECTIONS: CR 30 & CR 43, S. 0.1, W. INTO							CLIENT: Oxy				
LEGALS AND LAT/LONG: 40.200800, -104.662970							TASMAN PERSONNEL: Sierra Kirylo				
SOIL TYPES: Well Graded Sand - SW							SURFACE GRADIENT: North				
SOIL SAMPLING							FACILITY INFRASTRUCTURE				
Date/Time	Soil Sample ID	PID (ppm)	Visual	Olfactory	Photo?	Grab or Lab Sample?	EQUIPMENT		Quantity		
							Above Ground Storage Tank (AST)				
5/24/2021 14:30	WH-B01@8'	2.4	Organic Content	Organic Odor	Yes	Lab	Buried or Partially Buried Vessel				
5/24/2021 14:31	WH-N01@6'	1.6	No Staining	No Odor	Yes	N/A	Separator				
5/24/2021 14:32	WH-S01@6'	1.3	No Staining	No Odor	Yes	N/A	Emission Control Device (ECD)				
5/24/2021 14:33	WH-E01@6'	1.7	No Staining	No Odor	Yes	N/A	Dump Line				
5/24/2021 14:34	WH-W01@6'	1.8	No Staining	No Odor	Yes	N/A	Wellhead		1		
5/24/2021 14:35	WH-BG01@8'	1.3	No Staining	No Odor	Yes	Lab	Flowline				
5/24/2021 14:36	WHS-N01@3"	1.0	Organic Content	No Odor	Yes	N/A	Other:				
5/24/2021 14:37	WHS-S01@3"	1.4	No Staining	No Odor	Yes	N/A	Soil Loads Removed				
5/24/2021 14:38	WHS-E01@3"	1.4	No Staining	No Odor	Yes	N/A	IMPACTED SOIL IDENTIFIED?				
5/24/2021 14:39	WHS-W01@3"	1.8	No Staining	No Odor	Yes	N/A	ESTIMATED VOLUME OF IMPACTS:				
							Date	Number	CY		
								Total Removed	0	0	
							Disposal Facility:				
							Groundwater Recovery				
							DATE GW ENCOUNTERED:			DEPTH:	
							GROUNDWATER IN CONTACT WITH IMPACTED SOIL?				
							LNAPL OR SHEEN OBSERVED ON GW?				
GROUNDWATER SAMPLING							Date		BBLs		
Date/Time	Groundwater Sample ID	Depth Collected	Turbid?	Sheen?	Odor?	Photo?					
									Total Removed	0	
							Disposal Facility:				

Photographic Log

					
Equipment ID:		Equipment Type:	Equipment ID:		Equipment Type:
Material:	Volume:	Contents:	Material:	Volume:	Contents:
Notes/Conditions:			Notes/Conditions: WH-B01@8', WH-N01@6', WH-S01@6', WH-E01@6' and WH-W01@6' facing north		

Photographic Log

					
Equipment ID:		Equipment Type:	Equipment ID:		Equipment Type:
Material:	Volume:	Contents:	Material:	Volume:	Contents:
Notes/Conditions: WHS-N01@3", WHS-S01@3", WHS-E01@3" and WHS-W01@3" taken facing west			Notes/Conditions: WH-BG01@8" southwest of the excavation, picture taken facing east		