

Inspection Photos
Location Name: Dry Creek Federal 1-14
Location ID: 316764



Photo 1. Overview of location taken facing north. Stained soil in front of wellhead.



Photo 2. Close-up of stained soil from Photo 1.



Inspection Photos
Location Name: Dry Creek Federal 1-14
Location ID: 316764



Photo 3. Stained soil in unlit flare pit.



Photo 4. Venting occurring from tank labeled "vent tank."