

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC KNIGHT-67S95W /4NWNE

Location ID: 311549



Photo #4008 from entrance to location.



Photo #4009 from entrance to location.

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC KNIGHT-67S95W /4NWNE

Location ID: 311549



Photo #4010 wellhead sign weathered and not legible.



Photo #4011 location lacks stabilization.

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC KNIGHT-67S95W /4NWNE

Location ID: 311549



**Photo #4012 Location lacks stabilization.**



**Photo #4013 No form of tracking BMP located at the entrance to location.**